Block 1 West Side

Franklin St. to Water St.

Original Condition

10 Original Trees

- 8 Locust, 2 Pear
- O Planter Beds
- No Irrigation

- Roots Lifting Bricks
- Included Bark ("V" like junction; causes weakness)
- Weak Branching Structure
- ADA issues





Block 1 West Side Franklin St. to Water St. New Condition

4 Newly Planted Trees

- 2 Hornbeams
- 2 Japanese Zelkovas

New Additions

- Concrete Root Wells
- New Tree Grates
- 3 Planter Beds
- Planter Irrigation
- ADA Compliant



Block 1 East Side Canal St. to Park St. Original Condition

6 Original Trees

- 4 Locust, 2 Pear
- 0 Planter Beds
- No Irrigation

- Trunk Decay
- Internal Decay
- Circling Roots
- Top Dieback
- Mid-sidewalk
 ADA issues



Block 1 East Side Canal St. to Park St. New Condition____

7 Newly Planted Trees

 3 Crabapple, 2 Male Ginkgo, 2 Pear (both transplanted from West Side of Block)

New Additions

- Concrete Root Wells
- New Tree Grates
- 2 Planter Beds
- Planter Irrigation
- ADA Compliant





Block 2 West Side Water St. to Factory St. New Condition

6 Newly Planted Trees

5 Male Ginkgo Trees, 1 Japanese Lilac
 Tree


New Additions

- Concrete Root Wells
- New Tree Grates
- 6 Planter Beds
- Planter Bed Irrigation
- ADA Compliant



Japanese Lilac Tree





5 Original Trees

O Planter Beds

Dead Branches

No Irrigation

Remaining Blocks 3 through 5

54 Existing Trees

- 35 Locust
- 10 Red Maple
- 8 Linden
- 1 Pear



- Winter damage
- Mid-sidewalk ADA Issues
- Overgrowth
- Wire Issues
- Raised Roots & Bricks
- Dead Trees & Branches
- Cankers
- Locust trees drop many leaves and pods
- Linden trees are subject to Aphid infestations, resulting in staining of sidewalks and furnishings

Replacement Trees

Selected based on

- Tolerance to salt, drought,
 pollution, insect & disease
 problems, and aesthetic appeal
- Block Design will dictate trees & planter beds

• Include

- Hornbeam
- Male Ginkgo
- Pear
- Crabapple
- Red Maple
- Japanese Zelkova





Pear Tree